





COMPRESSOR MOTOR-END BEARING HAVING OIL LEAKAGE PATH  
 Applicant: Nieter; Serial No. 10/728,309  
 REPLACEMENT DRAWINGS






**FIG. 1**  
 Prior Art



**FIG. 2**  
 Prior Art

COMPRESSOR MOTOR-END BEARING HAVING OIL LEAKAGE PATH  
 Applicant: Nieter; Serial No. 10/728,309  
 REPLACEMENT DRAWINGS



BEST AVAILABLE COPY